

NOTICE TO MARINERS

Berwick Bank Wind Farm Limited - Notice to Mariners. Issue Date 13/10/2026 (Issue 01).

Overview

Mariners are advised that Berwick Bank Wind Farm Limited (BBWFL) will be returning to the Berwick Bank Wind Farm Area to undertake further geophysical survey work. Figure 1 displays the Mariner Cautionary Area for all marine traffic, with respective co-ordinates listed in Table 1.

The survey will focus upon the southern half of the wind farm area, with an additional survey in the north of the wind farm area. As towed equipment will be deployed, BBWFL are engaging with static gear fishers and have advised of specific areas in which gear should be cleared. A support vessel will be present to work alongside the survey vessel. An offshore fisheries liaison officer (OFLO) will be on the survey vessel.

The survey work is being undertaken by TGS and will be conducted by the Ramform Vanguard vessel. The support vessel details will be confirmed in an updated Notice to Mariners in advance of commencement of the survey. Vessels will arrive on site from 04 November at the earliest.

Survey Duration

The survey is anticipated to take approximately 2 weeks. To account for all eventualities including weather delays, we would like to extend the duration of notice validity to 30 November 2026.

Survey Tasks

The survey will involve deployment of towed equipment including Multi Beam Echosounder, Ultra-High Resolution Seismic and Sub-bottom profiler –Ultra Short Baseline.

As a consequence of the equipment being deployed and the modes of operation, all mariners are advised to keep a safe clearance distance of no less than 500 m from the vessel(s). In addition to the OFLO on board the survey vessel, Onshore Fisheries Liaison Officer services are available. Please see below for contact details.




Figure 1: Berwick Bank Wind Farm Site Boundary and Mariner Cautionary Area

Table 1 – Mariner Cautionary Area Coordinates

Ref	Lat (DD)	Lon (DD)	DDM	DDM
1	56.11893114	-1.68112234	56° 7.136' N	001° 40.867' W
2	56.27355225	-1.97295606	56° 16.413' N	001° 58.377' W
3	56.42895307	-1.77094557	56° 25.737' N	001° 46.257' W
4	56.45012613	-1.64695529	56° 27.008' N	001° 38.817' W
5	56.21470297	-1.2843713	56° 12.882' N	001° 17.062' W
6	56.11362426	-1.25348779	56° 6.817' N	001° 15.209' W

Offshore Survey and Scouting/Guard Vessels

Survey Vessel Contact Details



Ramform Vanguard	
Vessel Call Sign: C6JFS	Bridge: +870 773 162 712
IMO: 9188714	Captain: +47 67 51 49 62/64
MMSI: 311001861	Party Chief Tel: +47 6751 4967

Further marine enquiries should be addressed to the following person:

Marc Boon (Operations Business Manager)

Tel: +44 7740 753366

Email: marc.boon@tgs.com

Support Vessel Contact Details

To be confirmed in next issue of Notice to Mariners.

Contact Details – Onshore Fisheries Liaison

Onshore fisheries liaison for this survey will be co-ordinated by Brown and May Marine. If there are commercial fishery queries, please contact Sophie Farenden: +44 (0)7525 128344 or email: sophie.farenden@brownmay.com or zoe@brownmay.com.

There will be an offshore fisheries liaison officer (OFLO) aboard the survey vessels.

Further details are available from:

Kerrie Craig
SSE Renewables
Inveralmond House
200 Dunkeld Road
Perth, PH1 3AQ